

SOLD – Thanks Eric and Trish

1990 Volkswagen Vanagon Multivan

The only recreational vehicle with a soul. This ain't your hippy uncle's VW but he'll wish he'd seen it first!!

Powered by 1992 Subaru EJ22 Engine
Kennedy Engine Performance Conversion w/ Smog Compliance Documentation

Dependable Subaru engine increased available horsepower and torque by 50% while increasing fuel efficiency by 25%. The Vanagon Subaru engine conversion is accepted as the most common, best supported engine upgrade for the Volkswagen Vanagon and provides a powerplant that will make the van fun and trustworthy on the road.

Fresh Automatic 3 speed Transaxle, Cruise Control, Power Windows, Mirrors, and Door Locks. All available options.

Sleeps 4 and seats 7 comfortably. PopTop, Swivel passenger seat, convertible rear bench/bed, removable jump seats, convertible awning.

The following items are representative of the areas of the vehicle which have been restored or replaced to result in a dependable vehicle suitable for holiday and daily driving.

- Bearings
- Brakes
- Radiator
- Coolant Piping
- Wiring
- Gauges
- Stereo
- Undercoating
- Upholstery
- Ronal R28 Wheels w/ Dunlop Tires

Vehicle (not including paint) is restored with special attention paid to mechanical restoration which has been documented. All receipts for parts and services are cataloged and will be handed over with delivery of vehicle.

This Vanagon is one of the cleanest, best running vans in North America. The entire restoration and upgrade process has been completed since 11/2003 and is documented at <http://www.weidefamily.net/vanagon/>

See the vehicle featured on the following websites:

<http://forums.vwvortex.com>

<http://groups.yahoo.com/group/subaruvanagon/>

Itemized restoration and remaining defects detailed below.



\$16,000

Brent Weide
Portland, Oregon

1990 Volkswagen Vanagon Multivan Restoration Itemization

Upgrade						
Part Description	Part#	Brand	Malady	Actl Cost	Date	Location
CD Changer	CD-A08	Blaunpunkt	upgrade	\$ 130.00	1/8/2003	ebay - Private Party
Universal Mud Flaps			upgrade	\$ 8.00	2/1/2003	GIJoes
Sound Proof Doors/Hatch			upgrade	\$ 18.00	2/19/2003	Home Depot
Front Speakers – 6" components		JLAudio	upgrade	\$ 80.00	11/1/2003	ebay
Halogen Light Bulbs - Blue			upgrade	\$ 12.99	11/20/2003	GIJoes
Retrofit Eurovan Hella Dome Light - Front		Hella	upgrade	\$ 12.00	11/20/2003	Portland import used
Reading Lights/Fluorescent Fixtures			upgrade	\$ 20.00	12/1/2003	Home Depot
Replacement Stereo	Orlando	Blaunpunkt	upgrade	\$ 280.00	12/1/2003	ebay
Steering Wheel Wrap Leather			upgrade	\$ 30.00	12/5/2003	VW Café
Wheels	R28	Ronal	upgrade	\$ 400.00	12/8/2003	Private Party (ebay)
Tires	SP5000	Dunlop	upgrade	\$ 240.00	12/8/2003	Private Party (ebay)
Wheel Spacers from Ronal		Ronal	upgrade	\$ 135.00	12/8/2003	Ronal
Stereo Remote	Series 5	Blaunpunkt	upgrade	\$ 32.00	12/15/2003	ebay
Insulating Sheets (2) for soundproofing			upgrade	\$ 20.00	12/15/2003	Home Depot
Replacement Rear Speakers - 5 1/4"		Rockford Fosgate	upgrade	\$ 70.00	12/15/2003	Good Guys
Car Mats			upgrade	\$ 20.00	12/15/2003	Cosctco
Retrofit Eurovan Hella Dome Light - Rear		Hella	upgrade	\$ 12.00	11/1/2004	n/a
Sunroof		Crown Tops	upgrade	\$ 65.00	2/28/2005	eBay
SubTotal				\$ 1,584.99		
Restoration						
Part Description	Part#	Brand	Malady	Actl Cost	Date	Location
Replacement Mirrors (lens' only)				\$ 47.23	1/16/2003	http://www.automirrors.net
Vinyl for reupholstery of door panel				\$ 12.00	2/1/2003	Fabric Place
Contact Cement for upholstery				\$ 4.00	2/2/2003	Fabric Place
Carpet Pad for Rear Cabin				\$ 19.00	2/20/2003	Home Depot
Passenger Side Power Window Motor			broken	\$ -	11/1/2003	Repaired in place
Driver Side Power Door Lock Actuator			broken	\$ 40.00	2/20/2005	Replaced
Gray (w/ cloth insert) sliding door panel			damaged	\$ -	11/1/2003	Repaired in place
Replacement Fluorescent Fixture			broken	\$ -	11/1/2003	repaired
Condition Air Dam			worn	\$ -	11/1/2003	GIJoes
Sliding Door Hinge Lever Assembly				\$ 25.00	11/1/2003	ebay
Undercoating				\$ 20.00	11/1/2003	GIJoes
Cabinet Tee-Molding color: -gray				\$ 10.00	11/12/2003	Go Westy
Cover for Wiper Fluid Fill Cap			missing	\$ 6.00	11/12/2003	Go Westy
Top Mount Antenna			busted/worn	\$ 9.95	11/12/2003	Go Westy
Aftermarket Curtain Glider			busted/worn	\$ 4.20	11/12/2003	Go Westy
Windshield Wiper Arms for Front			worn	\$ -	11/15/2003	Repaired/Repainted
Re-Condition Pop-Top GelCoat Finish			worn	\$ -	11/17/2003	Penetrol Rust Control/Primer
Replacement Driver Middle Window			broken by bb gun	\$ 40.00	11/18/2003	Portland import used
2 headlights and 2 high beam rectangular lights (for '90)			broken	\$ 10.00	11/18/2003	Portland import used
Rear logos (Vanagon & Volkswagen - not symbol)			missing	\$ 10.00	11/18/2003	Portland import used
Rear passenger ash tray (fits in rear panel by seat)			broken	\$ 10.00	11/18/2003	Portland import used
Rear Wiper Arm Cap			missing	\$ 0.50	11/18/2003	Portland import used
Labor for installation of Middle Window			broken by bb gun	\$ 45.00	11/21/2003	Speed Auto Glass
Antenna			busted/worn	\$ 13.66	12/11/2003	BusDepot
Replace Electic Window Controls			broken	\$ 59.00	12/15/2003	Auto Electric
Gray Screw Covers for Headliner			missing	\$ 5.00	9/1/2004	
Auto Transmission Rebuild			worn	\$ 775.00	10/1/2004	Import Transmission Exchange
Genuine Mud Flaps			missing	\$ 60.00	11/1/2004	Bus Depot
CV Axles			worn	\$ 170.00	11/1/2004	Vanagon Café
Brake Pads Front			worn		11/1/2004	Bus Depot
Brake Shoes Rear			worn		11/1/2004	Bus Depot
Brake Hardware Rear			worn		11/1/2004	Bus Depot
Wheel Bearings - All			worn	\$ 43.00	11/1/2004	Bus Depot
Jumper Seat Left Side Panel Cap			missing	\$ 10.00	12/7/2004	Stuart - Private Party -

Swivel Seat Adapter and Plate	upgrade	\$	50.00	2/15/2005	Portland Craig - Private Party - Ebay
-------------------------------	---------	----	-------	-----------	---

SubTotal

\$ 1,498.54

Engine Conversion						
Part Description	Part#	Brand	Malady	Actl Cost	Date	Location
Basic kit for automatic; adapter plate, flexplate, bolts		KEP	conversion	\$480.00	12/17/2003	http://www.kennedyeng.com
Wiring instructions. 5 pages plus 6 ft. long drawing of harness		KEP	conversion	\$20.00	12/17/2003	http://www.kennedyeng.com
Intake air duct specify '80-83 air or '83+, not needed on Syncro 4WD		KEP	conversion	\$25.00	12/17/2003	http://www.kennedyeng.com
Engine crossmember, fits to Subaru rubber mounts. Specify: '80-83 , '83+ or 4WD		KEP	conversion	\$120.00	12/17/2003	http://www.kennedyeng.com
Heat shield. 33" x 8½" steel replaces part of original Vanagon shield. '83+		KEP	conversion	\$18.00	12/17/2003	http://www.kennedyeng.com
Exhaust header - option Jet Coat (rust inhibitor) add \$50		KEP	conversion	\$220.00	12/17/2003	http://www.kennedyeng.com
Catalytic converter and muffler		KEP	conversion	\$190.00	12/17/2003	http://www.kennedyeng.com
Radiator petcocks and fitting. Simplifies bleeding system.		KEP	conversion	\$20.00	12/17/2003	http://www.kennedyeng.com
Throttle bracket		KEP	conversion	\$20.00	12/17/2003	http://www.kennedyeng.com
Air filter and intake muffler		KEP	conversion	\$85.00	12/17/2003	http://www.kennedyeng.com
Shipping for KEP Kit		KEP	conversion	\$66.00	12/17/2003	http://www.kennedyeng.com
Subaru Engine EJ22		Subaru	conversion	\$900.00	11/20/2003	John Lemley - johnlem@ix.netcom.com
Subaru Harness and Misc Parts		Subaru	conversion	\$0.00	11/20/2003	John Lemley - johnlem@ix.netcom.com
Shortened OilPan		SmallCar	conversion		12/20/2003	http://www.SmallCar.com
Coolant Bypass Kit		SmallCar	conversion		12/20/2003	http://www.SmallCar.com
Subaru Power Steering Pressure Hose - 4 or 6 Cylinder	# HPS	SmallCar	conversion	\$49.95	12/20/2003	http://www.SmallCar.com
Crankshaft Seal	806733010	KP	conversion	\$3.38	2/2/2004	http://www.importpartsauthority.com/
Power Steering Belt	5PK890B	BANDO	conversion	\$8.60	2/2/2004	http://www.importpartsauthority.com/
A/c Belt	4PK905	CONTINENTAL	conversion	\$7.68	2/2/2004	http://www.importpartsauthority.com/
Timing Belt	TB172B	BANDO	conversion	\$23.28	2/2/2004	http://www.importpartsauthority.com/
Intake Manifold Gasket	14035AA290	STONE	conversion	\$4.96	2/2/2004	http://www.importpartsauthority.com/
Ignition Wire Set	3577435	OPPARTS	conversion	\$25.66	2/2/2004	http://www.importpartsauthority.com/
Spark Plug	BKR6E11	NGK	conversion	\$7.24	2/2/2004	http://www.importpartsauthority.com/
Valve Cover Gasket Set	13294AA011KIT	STONE	conversion	\$19.45	2/2/2004	http://www.importpartsauthority.com/
Thermostat	21200AA07177	MOTORAD	conversion	\$11.48	2/2/2004	http://www.importpartsauthority.com/
Thermostat O-ring	1632562010	STONE	conversion	\$2.06	2/2/2004	http://www.importpartsauthority.com/
Oil Filter	15208AA021A	UNION SANGYO	conversion	\$4.60	2/2/2004	http://www.importpartsauthority.com/
Water Pump	21111AA002	ATSUGI	conversion	\$49.30	2/2/2004	http://www.importpartsauthority.com/
Oil Seal	FELBS40638	FELPRO	conversion	\$19.48	2/8/2004	Schuck's Auto Supply
TCS45918 FELPRO TIMING COVER	FELTCS45918	FELPRO	conversion	\$12.88	2/8/2004	Schuck's Auto Supply
Vanagon CV Joint Boot Kits, Set of 4, 80-91	2452253794		conversion	\$28.95		volkscafe.com
Power steering fluid			conversion			Schuck's Auto Supply
AT Fluid			conversion			Schuck's Auto Supply
Coolant			conversion			Schuck's Auto Supply
Misc Brass Fittings / Misc Stainless Clamps			conversion	\$25.00	3/9/2004	http://www.fittingsandadapters.com/
Muffler Clamp	8946K36	McMaster	conversion	\$6.58		http://www.mcmaster.com/

muffler bracket (custom fabricated)	Tom Shiels	conversion	\$40.00	6/9/2004	Tom Shiels - shiels.t.w@cogeco.ca
-------------------------------------	------------	------------	---------	----------	-----------------------------------

SubTotal **\$2,514.53**

TOTAL	\$5,598.06				
--------------	-------------------	--	--	--	--

1990 Volkswagen Vanagon Multivan

Defect Itemization

As I want to be fully honest about the van I made up a list of the bad things about it. I had intended to rectify each of these areas and have taken steps to resolve. None of them are what I consider to be even medium priority but I will leave that up to you to decide.

Vehicle Defects	
Defect Description	Notes
Passenger Rear Fender	Ding on fender rim is repaired, unpainted (ready for paint) Small areas (most smaller than a dime) of surface rust in following areas
Small Areas of external surface rust	<ul style="list-style-type: none"> • driver foot step pad. • passenger foot step pad. • below driver middle sliding window (treated) • below passenger middle sliding window
Paint finish is very good but has multiple touched up scratches	Have touched up most scratches and am selling with proper paint and clearcoat touch up kit just purchased from www.paintscratch.com
Rear bumper	has been fully repaired from where previous owner cut it to install hitch. I can and will paint it as per the wishes of the new owner.
Air Conditioning	A/C is not hooked up. I can and will retrieve the necessary hoses from the subaru engine dealer or am willing to negotiate price based on new owners wishes.
Rear Hatch	Hatch has what I consider to be a large area of rust corrosion on the bottom lower corner. I have purchased and will include a replacement VW Vanagon hatch lid, complete with wiper/washer, lock, and glass.

Why am I selling?

I worked long and hard on this Vanagon and am very proud and pleased how the finished product turned out. During the latter phase of the Vanagon restore my son took an active interest in the project and began helping out. This fact, coupled with the fact that I'm crazy about VW Vanagons, led me to my next project, the restoration of a 1991 Orly Blue Multivan. I'll be converting the drivetrain to Subaru power just like I did with this van.

This van has been a blast to work on and I hope you have safe travels in her.